


SITE NAME: Wilcox Refinery TDD#: S06-9606-026  
 PHOTO#: 101 PHOTOGRAPHER/WITNESS: Ben Martich/David Crow  
 DATE: 06/13/97 TIME: 0827 DIRECTION: Southwest  
 The (b) (6) (on-site).



SITE NAME: Wilcox Refinery TDD#: S06-9606-026  
 PHOTO#: 102 PHOTOGRAPHER/WITNESS: David Crow/Ben Martich  
 DATE: 06/13/97 TIME: 0929 DIRECTION: West  
 The (b) (6) (on-site) with abandoned oil storage tanks in the background.



SITE NAME: Wilcox Refinery TDD#: S06-9606-026  
 PHOTO#: 103 PHOTOGRAPHER/WITNESS: David Crow/Ben Martich  
 DATE: 06/13/97 TIME: 0901 DIRECTION: South  
 Abandoned oil storage tank located in the northwestern portion of the site.



SITE NAME: Wilcox Refinery TDD#: S06-9606-026  
 PHOTO#: 104 PHOTOGRAPHER/WITNESS: David Crow/Ben Martich  
 DATE: 06/13/97 TIME: 0945 DIRECTION: Southwest  
 1st Assembly Church of God located in the northwestern corner of the site.